

RADIO RECEIVER SUPERIMPOSED ON CHANNEL 2 OF SLAVE RECORDER. IS THIS PERMANENT HOOKUP? S-BAND SIGNALS ALL DOWN 0600Z. ALL OTHER EQUIP OPERATED SATISFACTORILY.

END OF MESSAGE